
187



	PWFB					7./	2 0		
CORN	IER RECC	PRD	D	ocument Nu	mber _	E.	186		
City of	BURBANK		Count	ty of Los Ang	geles, Ca	alifornia		_	
Brief Legal D	escription C/L HAT	TERAS ST. & R	OSE ST C	L MONUME	NT PR	ESERVATIO	N		
			ERTYPE	- 	N.	N. COORDINATES (Optional)			
	100	Govt. Comer	☐ Co	ntrol 🗌	E.		NAD27 🗆		
		Meander	☐ Pro	perty			NAD2/ LI	NAD83	
		Rancho	□ Ott	a		v rt. Datum:	NGVD29 □	NAVD88	
		Date of Survey	9-Mar-04	·		eas. Units:	Metric	Imperial	
Comer -	Left as found	☐ Found	& tagged] Establi	shed [Reestat	olished	Rebuilt 🛛	
Identification see plat;	and type of corne	r found: Evidenc	e used to ide	ntify or proc	edure us	sed to establ	ish or reestab	lish the corner:	
distances m	easured horizontal	;							
		5			- 1				
								172	
							BE		
A description see plat;	n of the physical co	ndition of the mor	nument as fou	ind and as se	et or rese	et:	2		
-									
	SURVEYO	R'S STATEMEN	т ,			l.	SIONAL LAND		
This Corner F	Record was prepare	ed by me or under	my direction	in conformar	nce	ROF.	JOHN P. OSTI	131	
with the Land	Surveyors' Act on	22-Mar-04			·		DOA 09-30-	05	
Signad A	Of Ostly	P.L.S. or R.C.	E No. 5	691		1.	NO. 5691		
Signed	1		E. NO	1 6091			TE OF CALIF	25.4	
	COUNTYSUE	RVEYOR'S STATE	EMENT						
This Corner F	Record was received	APR 15 26	104			-	SEOL	AND SURVEL	
1261	ed and filed _ MAY						\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	- CE 3	
(1)	1 Let 10 /11	P.L.S. or R.C.	E No.				(2/2)	LS 6363	
Signed No	79 1000	M_F.L.S. OF H.C.	□. NO.				1 . \ EX	" IEIO	



TIES-FILED AS SUBMITTED

County Surveyor's Comment